

TO WHOM SO EVER IT MAY CONCERN

BUILDING SAFETY CERTIFICATE

It is certified that the building of Vibgyor World School V.P.O. Piplage Tehsil Bhunter Distt. Kullu HP has been inspected by the Assistant Engineer Bhunter Sub Division HPPWD Bhunter. At present the school being run in ground floor, 1st floor and 2nd floor of the building. As per his visual inspection the building seems to be safe to run school classes for the academic year 2023-24 under normal condition. However structural stability cannot be ascertained due to non availability of structural design, drawings and IS specification required for the building construction. This certificate is being issued purely on the basis of visual inspection and issuance of this certificate does not confer any legal and financial liabilities on the issuer. Further no addition & alteration be carried out in the building and if any addition & alteration is required fresh safety certificate be obtained.


**Executive Engineer,
Kullu Division,
HPPWD Kullu.**

No.PW/KD/WA-I/Building/2023

17398-99

Dated:-1-3-23

Copy to the Assistant Engineer Bhunter Sub Division HPPWD Bhunter with reference to his office letter No. PW/BSD/Building Safety certificate/2021-22-2526 dated 28.2.2023 for information and necessary action.

Copy to the Principal Vibgyor World School V.P.O. Piplage Tehsil Bhunter Distt. Kullu HP.


**Executive Engineer,
Kullu Division,
HPPWD Kullu.**